


WEEKLY SNAPSHOT









Toilet partitions in the amenities

ADMINISTRATION BUILDING

- External roof cladding to steel roof structure and roofing continues on Level 9
- Plant and equipment fit out and internal light weight walls are installed on Level 9
- Framing to amenities on Level 8
- Curtain wall installed and tiling to amenities on Level 7
- Completion of Curtain wall on Level 6
- Amenities fit out to toilet partitions and wall framing on Level 5
- Internal walls and gyprock sheeting installed on Level 4
- Setting and painting of internal walls on Level 3
- Ceiling framing underway on Level 2
- Sheeting and setting to feature ceilings, stone cladding and planters added to balcony on Level 1
- Completing installation of air locks and sheeting and setting to ceilings on Ground Level

EXTERNAL SPACES

- Concreting, installation of seats and planter walls on external works outside of Admin building/Civic Plaza space
- Concreting and pouring of footings continue on Bremer Street cross over and works continue on perimeter walls

FAST FACT

 170 workers across the Library, Civic Plaza and Administration Building this week.